

VEHICLE CONDITION REPORT



| Name and Surname of evaluator | | NOBLE NGWENYA | | | |
|--------------------------------------|----------------|----------------------|----------------|--------------------|-------------------|
| AUCTION DATE | 1-2 MARCH 2022 | REGISTRATION NUMBER | JSD153NW | | |
| VEHICLE MAKE | MAHINDRA | MODEL | SCORPIO PIK UP | | |
| COLOUR | WHITE | YEAR MODEL | 2016 | | |
| RUNNER / NON RUNNER | RUNNER | TRANSMISSION | MANUAL | | |
| OVERALL CONDITION | GOOD | ODOMETER READING | 181553 | | |
| Condition | Good | FAIR | Poor | Comments: | |
| FRONT BUMPER | * | | | | |
| FRONT VALANCE | | | | | |
| FRONT NUMBER PLATE | * | | | | |
| GRILL | * | | | | |
| FRONT LIGHT | * | | | | |
| BONNET | | * | | SCRATCHED | |
| WINDSCREEN | * | | | | |
| WINDSCREEN WIPERS | * | | | | |
| LEFT FRONT FENDER | | * | | SCRATCHED | |
| LEFT FRONT DOOR | * | | | | |
| LEFT REAR DOOR | | | | | |
| LEFT REAR FENDER | | * | | SCRATCHED | |
| REAR VALANCE | * | | | | |
| REAR NUMBER PLATE | * | | | | |
| REAR BUMPER | * | | | | |
| BOOT/LDV LOADING REAR | * | | | | |
| REAR LIGHTS | * | | | | |
| RIGHT REAR FENDER | | * | | SCRATCHED | |
| RIGHT REAR DOOR | | | | | |
| RIGHT FRONT DOOR | | * | | SCRATCHED | |
| RIGHT FRONT FENDER | | * | | SCRATCHED | |
| ROOF FROM OUTSIDE | | * | | SCRATCHED | |
| OTHER WINDOWS | * | | | | |
| CARPETS | * | | | | |
| SEATS | | * | | DRIVER'S SEAT TORN | |
| EQUIPMENT PRESENT | YES/NO | Comment: | | TYRES | % |
| SPAREWHEEL | Y | | | LEFT FRONT | 90 |
| JACK | Y | | | LEFT REAR | 90 |
| WHEELSPANNER | Y | | | RIGHT FRONT | 90 |
| RADIO | Y | | | RIGHT REAR | 90 |
| SERVICE BOOKS | N | | | SPAREWHEEL | 90 |
| KEYS PRESENT | Y | | | ENGINE NUMBER | |
| SPARE KEYS | Y | | | VIN NUMBER | MA1TW2MMNG2E42799 |
| BATTERY | Y | | | DASHBOARD LIGHTS | N |
| EXTRAS | Y | TOW BAR | | MECHANICAL DEFECTS | N |

BULL BAR

