

VEHICLE CONDITION REPORT



| Name and Surname of evaluator | | NOBLE NGWENYA | | | |
|--------------------------------------|----------------|----------------------|----------|--------------------|-------------------|
| AUCTION DATE | 5-6 APRIL 2022 | REGISTRATION NUMBER | BG85PLGP | | |
| VEHICLE MAKE | MERCEDES BENZ | MODEL | C180 CGI | | |
| COLOUR | GREY | YEAR MODEL | 2011 | | |
| RUNNER / NON RUNNER | RUNNER | TRANSMISSION | AUTO | | |
| OVERALL CONDITION | GOOD | ODOMETER READING | 155328 | | |
| Condition | Good | FAIR | Poor | Comments: | |
| FRONT BUMPER | | * | | SCRATCHED | |
| FRONT VALANCE | | | | | |
| FRONT NUMBER PLATE | * | | | | |
| GRILL | * | | | | |
| FRONT LIGHT | * | | | | |
| BONNET | * | | | | |
| WINDSCREEN | * | | | | |
| WINDSCREEN WIPERS | * | | | | |
| LEFT FRONT FENDER | * | | | | |
| LEFT FRONT DOOR | | * | | SCRATCHED | |
| LEFT REAR DOOR | * | | | | |
| LEFT REAR FENDER | * | | | | |
| REAR VALANCE | | | | | |
| REAR NUMBER PLATE | * | | | | |
| REAR BUMPER | | * | | SCRATCHED | |
| BOOT/LDV LOADING REAR | * | | | | |
| REAR LIGHTS | * | | | | |
| RIGHT REAR FENDER | * | | | | |
| RIGHT REAR DOOR | * | | | | |
| RIGHT FRONT DOOR | * | | | | |
| RIGHT FRONT FENDER | | * | | SCRATCHED | |
| ROOF FROM OUTSIDE | * | | | | |
| OTHER WINDOWS | * | | | | |
| CARPETS | * | | | | |
| SEATS | * | | | | |
| EQUIPMENT PRESENT | | COMMENTS | | TYRES | % |
| SPAREWHEEL | N | | | LEFT FRONT | 60 |
| JACK | Y | | | LEFT REAR | 60 |
| WHEELSPANNER | Y | | | RIGHT FRONT | 60 |
| RADIO | Y | | | RIGHT REAR | 60 |
| SERVICE BOOKS | N | | | SPAREWHEEL | |
| KEYS PRESENT | Y | | | ENGINE NUMBER | |
| SPARE KEYS | N | | | VIN NUMBER | WDD2040492R176846 |
| BATTERY | Y | | | DASHBOARD LIGHTS | N |
| EXTRAS | Y | SUNROOF | | MECHANICAL DEFECTS | N |

RESPRAYED

