

VEHICLE CONDITION REPORT



Name and Surname of evaluator		NOBLE NGWENYA			
AUCTION DATE	17 - 18 MAY 2022	REGISTRATION NUMBER	HS10YNGP		
VEHICLE MAKE	SUZUKI	MODEL	SUPERCARRY		
COLOUR	WHITE	YEAR MODEL	2018		
RUNNER / NON RUNNER	RUNNER	TRANSMISSION	MANUAL		
OVERALL CONDITION	GOOD	ODOMETER READING	174956		
Condition	Good	FAIR	Poor	Comments:	
FRONT BUMPER		*		SCRATCED	
FRONT VALANCE	*				
FRONT NUMBER PLATE	*				
GRILL	*				
FRONT LIGHT	*				
BONNET	*				
WINDSCREEN	*				
WINDSCREEN WIPERS	*				
LEFT FRONT FENDER	*				
LEFT FRONT DOOR	*				
LEFT REAR DOOR	*				
LEFT REAR FENDER	*				
REAR VALANCE					
REAR NUMBER PLATE	*				
REAR BUMPER	*				
BOOT/LDV LOADING REAR	*				
REAR LIGHTS	*				
RIGHT REAR FENDER	*				
RIGHT REAR DOOR	*				
RIGHT FRONT DOOR		*		SCRATCHED	
RIGHT FRONT FENDER	*				
ROOF FROM OUTSIDE	*				
OTHER WINDOWS	*				
CARPETS	*				
SEATS	*				
EQUIPMENT PRESENT		COMMENTS		TYRES	%
SPAREWHEEL	Y			LEFT FRONT	100
JACK	N			LEFT REAR	100
WHEELSPANNER	N			RIGHT FRONT	100
RADIO	N			RIGHT REAR	100
SERVICE BOOKS	N			SPAREWHEEL	100
KEYS PRESENT	Y			ENGINE NUMBER	
SPARE KEYS	N			VIN NUMBER	MA3EDA53T00118000
BATTERY	Y			DASHBOARD LIGHTS	N
EXTRAS	N			MECHANICAL DEFECTS	N

RESPRAYED				
-----------	--	--	--	--

