

VEHICLE CONDITION REPORT




Name and Surname of evaluator		Sihle Skosana			
AUCTION DATE	11 - 12 August 2021	REGISTRATION NUMBER	JDC374NW		
VEHICLE MAKE	Opel	MODEL	Corsa Hatch		
COLOUR	Red	YEAR MODEL	2014		
RUNNER / NON RUNNER	Runner	TRANSMISSION	Manual		
OVERALL CONDITION	Good	ODOMETER READING	156714km		
Condition	Good	Fair	Poor	Comments:	
FRONT BUMPER	x				
FRONT VALANCE		x			
FRONT NUMBER PLATE	x				
GRILL	x				
FRONT LIGHT		x			
BONNET		x			
WINDSCREEN	x				
WINDSCREEN WIPERS	x				
LEFT FRONT FENDER		x			
LEFT FRONT DOOR	x				
LEFT REAR DOOR	x				
LEFT REAR FENDER	x				
REAR VALANCE					
REAR NUMBER PLATE	x				
REAR BUMPER	x				
BOOT/LDV LOADING REAR		x			
REAR LIGHTS		x			
RIGHT REAR FENDER			x		
RIGHT REAR DOOR			x		
RIGHT FRONT DOOR		x			
RIGHT FRONT FENDER	x				
ROOF FROM OUTSIDE	x				
OTHER WINDOWS	x				
CARPETS	x				
SEATS	x				
EQUIPMENT PRESENT	YES/NO	Comment:	TYRES		%
SPAREWHEEL	No		LEFT FRONT		80
JACK	No		LEFT REAR		80
WHEELSPANNER	No		RIGHT FRONT		80
RADIO	Yes		RIGHT REAR		80
SERVICE BOOKS	No		SPAREWHEEL		
KEYS PRESENT	Yes		ENGINE NUMBER	A14XER19D51953	
SPARE KEYS	No		VIN NUMBER	W0405DL68E4034569	
BATTERY	Yes		LICENSE DISK NUMBER	40110029B70	

EXTRAS	No		KILOMETERS IN	156714km
--------	----	--	---------------	----------

Spraywork Visible

|



□