

VEHICLE CONDITION REPORT



Name and Surname of evaluator		NOBLE NGWENYA			
AUCTION DATE	21-22 SEP 2021	REGISTRATION NUMBER	HPY071FS		
VEHICLE MAKE	MITSUBISHI	MODEL	ASX		
COLOUR	RED	YEAR MODEL	2013		
RUNNER / NON RUNNER	RUNNER	TRANSMISSION	MANUAL		
OVERAL CONDITION	GOOD	ODOMETER READING	145178		
Condition	Good	FAIR	Poor	Comments:	
FRONT BUMPER	*				
FRONT VALANCE					
FRONT NUMBER PLATE	*				
GRILL	*				
FRONT LIGHT	*				
BONNET	*				
WINDSCREEN	*				
WINDSCREEN WIPERS	*				
LEFT FRONT FENDER	*				
LEFT FRONT DOOR		*		SCRATCHED	
LEFT REAR DOOR		*		SCRATCHED	
LEFT REAR FENDER	*				
REAR VALANCE					
REAR NUMBER PLATE	*				
REAR BUMPER	*				
BOOT/LDV LOADING REAR	*				
REAR LIGHTS	*				
RIGHT REAR FENDER	*				
RIGHT REAR DOOR	*				
RIGHT FRONT DOOR	*				
RIGHT FRONT FENDER	*				
ROOF FROM OUTSIDE	*				
OTHER WINDOWS	*				
CARPETS	*				
SEATS	*				
EQUIPMENT PRESENT	YES/NO	Comment:	TYRES		%
SPAREWHEEL	Y		LEFT FRONT		80
JACK	Y		LEFT REAR		60
WHEELSPANNER	Y		RIGHT FRONT		80
RADIO	Y		RIGHT REAR		80
SERVICE BOOKS	Y		SPAREWHEEL		80
KEYS PRESENT	Y		ENGINE NUMBER	4B11LK5514	
SPARE KEYS	N		VIN NUMBER	JMYXNGA2WDZ001277	

BATTERY	Y		DASHBOARD LIGHTS	N
EXTRAS	N		MECHANICAL DEFECTS	N

”